

RAP056A

Navara D22 4WD Lower Ball Joint

We've redesigned the Lower Ball Joint for the Navara D22 4WD, to provide for an easier installation and a more accurate fit. It has been identified that due to the initial design from genuine, when the lower ball joint is fitted to the arm, the nut tightening design causes arm 'crush'. Subsequently when a replacement ball joint is fitted, it can potentially result in a fitment with insufficient interference. This is through no fault of the ball joint, it is due to the 'crush' in the arm. To overcome fitment issues with the replacement ball joint we have redesigned the nut, to allow for an extra 1mm of tightening ability, in addition to including a 2mm spacer washer for use if additional arm 'crush' is evident. If the replacement ball joints still do not fit up using the redesigned nut & the spacer washer, a new replacement arm is required. During the redesign process, we've also had 'flats' machined on the body flange to allow for a suitable holding surface to make installation more efficient.

When determining whether you need to fit an oversize or modified ball joint, careful inspection of the control arms is necessary. Any cracks, bends, distorted holes or other abnormalities indicate that the control arm also needs replacing.

Part Number: BJ4802
Description: Navara D22 4WD Lower
Bar Code: 9319478194472

E.& O.E. All pricing subject to GST.

Available Now!

VIC - Phone 1300 651 551 Fax 1300 651 451
QLD - Phone 1300 559 086 Fax 1300 559 842

