

# Cruiser & Hilux Rack Ends

## RE3810



Part Number: RE3810  
(replaces RE6438)  
Bar Code: 9319478425439  
Suit: Landcruiser 98-02 Rack End  
Replaces: OE# 45503-69015  
210mm overall length  
20x1.5 tre thread / 18x1.5 socket thread

## RE3811



Part Number: RE3811  
Bar Code: 9319478425446  
Suit: Landcruiser 03-on Rack End  
Replaces: OE# 45503-69025  
225mm overall length  
20x1.5 tre thread / 27x1.5 socket thread

## RE3840



Part Number: RE3840  
Bar Code: 9319478425453  
Suit: Hilux RZN21#, VZN21#, TRN21#  
KDN215 2WD 02-on Rack End  
Replaces: OE# 45503-39235  
275mm overall length  
15x1.5 tre thread / 22x1.5 socket thread

## RE3880



Part Number: RE3880  
Bar Code: 9319478432376  
Suit: Hilux KUN1#, KUN2#, GGN#  
2WD/4WD 05-on Rack End  
Replaces: OE# 45503-09321  
310mm overall length  
15x1.5 tre thread / 14x1.5 socket thread

# Available Now!

VIC - Phone 1300 651 551 Fax 1300 651 451  
QLD - Phone 1300 559 086 Fax 1300 559 842

